Newport Bench

037 4' Bench 137 5' Bench






ASSEMBLY INSTRUCTIONS

PLEASE READ INSTRUCTIONS COMPLETELY BEFORE BEGINNING.
Carefully remove contents from box. Make sure that all parts and hardware are included using the Parts List below.

Tools Required: 4mm Allen Wrench (included); #2 Phillips Head Screwdriver; Rubber Mallet.



WARRANTY QUESTIONS OR COMMENTS PLEASE CALL TOLL FREE AT 1-800-809-3114

ATTACH SIDE ASSEMBLIES TO SEAT ASSEMBLY

3

ATTACH BACK TO REAR LEGS



Align Left Side Assembly with seat assembly. Secure using (2) 80MM Hex Lags through the counter-bored

holes in front leg into pilot holes in front apron of seat assembly. Plug holes with (2) 5/8'' taps®.

Repeat process for Right Side.



Align counterbored holes in Rear Left Leg with Pilot holes in Back Assembly, ensuring that the

counter-bores in lower back are facing outward. Attach using (3) 80mm Hex Lags. Plug holes with (3) 5/8" taps®.

Repeat process for Right side.



ATTACH BACK ASSEMBLY TO SEAT




SECURE REAR SEAT CLEAT TO LOWER BACK (137 ONLY)



Secure Lower Back Assembly to Seat Assembly using (4) 80MM Hex Lags (3 for 037) thru coun-

ter-bored holes in lower back into pilot holes in seat supports. Plug holes with (4) 5/8" taps®.




Turn Assembly upside down. Secure aluminum seat cleat to lower back using (9) 3/4" Phillips Pan Head Screws.



ATTACH SEAT CLEAT TO SIDE ASSEMBLY



ATTACH STRETCHER TO SIDE ASSEMBLIES (137 ONLY)



Secure outer seat cleat to side assembly using (2) 1-1/4" Phillips Head Screws.

Repeat Process for other side.



Align counterbored holes in lower side stretcher with Pilot holes in long stretcher,

making sure that the aluminum in the long stretcher is facing down. Attach using (2) 80mm Hex Lags. Plug holes with (2) 5/8'' Bungs using rubber mallet.

Repeat process for other side.