

# (046) Portsmouth Dining Table rev. C (56In x 56In),

#### **Parts List:**

- (1) Table Top Assembly
- (2) Leg Assemblies
- (2) Leg Stretchers
- (2) Long Aprons
- (2) Short Aprons



#### Hardware:

46 (16) 3" Hex 1/4" Lags (16) 3/4" Pan Head Screws

## Tools Required: Phillip's Head Screwa

Phillip's Head Screwdriver 4MM Allen Wrench (Included)


### **Assembly Instructions**

**Step One: Set Up** 

**READ ENTIRE INSTRUCTIONS BEFORE BEGINNING!** Carefully remove contents from box. Make sure that all parts and hardware are included. Place Table Top upside down on a flat clean surface.

**Step Two: Leg Stretchers** 

Place Leg Stretchers between both Leg Assemblies aligning pre-drilled holes. Attach each end of both stretchers using (2) 3" Hex 1/4" Lags (Right Picture).



#### **Step Three: Apron Assembly**


Place Short Aprons between Long Aprons aligning pre-drilled holes. Attach using a 3" Hex 1/4" Lag on both sides of each Short Apron.



## **Step Four: Apron Attachment**



Place Apron Assembly on to Leg Assembly aligning pre-drilled holes in the Aluminum and Legs (Left Picture). Attach using (4) 3" Hex 1/4" Lags (Right Picture).



#### **Step Five: Base Attachment**

Place Base Assembly upside down and square on to the Table Top Assembly. Align Apron ends and sides with the center of the Table Top Assembly. Attach using (16) 3/4" Pan Head Screws.

